

CONDITION CHECK REPORT

BF No.	BK784343	CHASSIS No.	AT212-0055501	DATE	2022 / 2 / 14
--------	----------	-------------	---------------	------	---------------

1	TIMING BELT CHANGE		YES		KM	13	POWER WINDOW (R FRONT)	<input checked="" type="radio"/> OK	NG			NONE
2	COOLANT LEVEL	<input checked="" type="radio"/> OK	NG	LEAK			14 POWER WINDOW (L FRONT)	<input checked="" type="radio"/> OK	NG			NONE
3	ENGINE OIL LEVEL	<input checked="" type="radio"/> OK	NG	DIRT			15 POWER WINDOW (R REAR)	<input checked="" type="radio"/> OK	NG			NONE
4	OIL LEAKING	<input checked="" type="radio"/> OK	NG	SMALL	BIG		16 POWER WINDOW (L REAR)	<input checked="" type="radio"/> OK	NG			NONE
5	TIRE (R FRONT)	<input checked="" type="radio"/> OK	NG	175/70R14		RFT	17 A/C FITTED <small>※A/C 機能が付いているか</small>	<input checked="" type="radio"/> YES	NO			
6	TIRE (L FRONT)	<input checked="" type="radio"/> OK	NG	175/70R14		RFT	18 WIND BLOWS OK	<input checked="" type="radio"/> YES	NO			
7	TIRE (R REAR)	<input checked="" type="radio"/> OK	NG	175/70R14		RFT	19 A/C COOLS OK	<input checked="" type="radio"/> YES	NO			
8	TIRE (L REAR)	<input checked="" type="radio"/> OK	NG	175/70R14		RFT	20 INTERIOR CONDITION	<input checked="" type="radio"/> OK	NG	DIRT	SMOKING SMELL	OTHER SMELL
9	ENGINE NOISE	<input checked="" type="radio"/> OK	NG	E/G	OTHERS		21 CHECK / WARNING LAMP	<input checked="" type="radio"/> OK	E/G	ABS	AIRBAG	OTHER
10	ENGINE CONDITION	<input checked="" type="radio"/> OK	NG	IDLING	SMOKE		(COMMENT)				TESTER CHECK	
11	EXHAUST LEAK	<input checked="" type="radio"/> OK	NG	MUFFLER RUSTY	MISSING PARTS							
12	TRANSMISSION (AT / MT)	<input checked="" type="radio"/> OK	NG	SHOCK	NOISE	SLIP						
OPTION												
<input checked="" type="radio"/> RADIO		<input checked="" type="radio"/> C D										
(注意) オプション品が付いていて作動するものは「○」、付いていて作動しないものは「×」、オプション品が付いていないものは「無印」でお願いします。												
(注意) NGが入った項目は、窓ガラスに記載せずコメントにすべて記載をお願いします。オークションシートをチェックして、U3・B3以上の凹みキズ、フロントガラスの割れやヒビ(メーカーで困る)、その他目立つ破損部分があった場合は、写真撮影をお願いします。												

YARD	木更津・畑沢(SPX)	INSPECTER	高田	AA SHEET	✓
------	-------------	-----------	----	----------	---